



RAM®
CONSTRUCTION SERVICES

MARYGROVE CAMPUS BUILDING RESTORATION



Bill Brown



Bill VanMarter

ramservices.com



HISTORY

Marygrove was an all women's college established in Detroit in the 1920s.



1927

Marygrove
College is
established.

2018

Marygrove
Conservancy is
formed.

2020

RAM is awarded
work for 8 of the
oldest buildings.

1970

The transition
to a co-ed
institution.

2019

Marygrove College
closes due to lack of
funding and
enrollment.



HOW DO HISTORIC PROPERTIES FALL INTO DISREPAIR?

Budgets impacted by
undefined maintenance

Failure to plan for short
term and long term
maintenance





MARYGROVE CONSERVANCY

PROJECT PARTNERS



BDC



SMITHGROUP



RAM

SCOPE OF WORK

Masonry Repair

Brick Replacement

Repointing/Tuckpointing

Lintel Restoration

**Stone Replacement &
Restoration**

Cleaning & Restoration

Stone Patching

Basement Leak Repair

OVERVIEW



FACADE TYPES

3

Limestone facade with slate
roof tile


3

All brick

2

Brick with limestone cap





2020

RAM is awarded work for 8 of the oldest buildings

2023

Project concludes

20,404

WORK HOURS

2,550

WORK DAYS

10

AVG. CREW SIZE

2020

Work begins with removing fall hazards from Liberal Arts Building



IMMACULATA BUILDING

Focus Area #1



Brick Replacement & Repairs

Tuckpointing

Control Joints Installation

Stone Porch Reconstruction

Capstone Restoration



MINNACUBING



BRICK COLOR MATCHING





**BLENDED BRICK
REPLACEMENT**

5,872

**BRICKS
PLACED**



LINTEL REPAIR AND DAMAGED
BRICK REPLACEMENT



IMMEDIATE BUILDING



JIMMY ACCUBING BUILDING



LIBERAL ARTS BUILDING LIMESTONE

Focus Area #2



Brick & Masonry Repairs

**Stone Restoration
and Replacement**

Stair & Step Work

**Patching & Surface
Repairs**

Final Cleaning




LIBERARTE





LIBERARTE



LIBRARIES



LIBERALS



LIBERARTE



LIBERARIS



LIBBERTS




LIBERALS



ENTRANCE GATE

Focus Area #3






ENI FRANGE



EMERGENCY



RELEASE OF WATER



EMERGENCY REPAIRS



REPOINTING



HERITAGE FRAGMENT



344 TOTAL STONES

326 SALVAGED

18 REPLACED



DEMOLITION PHASE 1



EMERGENCY FRAGMENT



DEMOLITION PHASE 2



EMERGENCY



DEMOLITION PHASE 3



REINFRAGTE



ENIRGATE



FRANKLIN



ENIRGATE





STAY AHEAD OF REPAIRS

Schedule Regular Facade Assessments

Develop a Maintenance Plan

Budget for the Future





RAM[®]
CONSTRUCTION SERVICES

THANK YOU!

ramservices.com



Bill Brown



Bill VanMarter